



TOR for Wet Sweeper

Minimum Qualification: Class X passed

1. Monitor Treatment plant 24/7 and report to Technician for any issues.
1. Maintain and clean the Screen Chamber on Daily basis and dispose of the waste at required locations.
2. Daily operation of STP, monitor inflow and outflow.
3. Assist Plant Technician in carrying out the monthly Test to check the quality of water.
4. Check and maintain pumps, motors and any other equipment weekly and report to Technician.
5. Assist Technician in looking after the store and keep proper record of the materials.
6. Keep the surrounding clean and free from animals.
7. Any other work assigned by the Head/Chief.